Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO0966Work Order Type: WeatherizationAudit Name: 14014SO0966

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO0966 WINCHESTER, TN 37398

Alt. Client ID: FRANKLIN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO0966
Alt. Client ID: FRANKLIN

Work Order (Bid Form)
Work Order Name: 14014SO0966
Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 4

Measures

Measure 1 Gei	neral Air Sealing			Inspected				
	JLK ALL WINDOWS							
2. INTE	ERIOR AIR SEAL TO RED	DUCE CF	И'S BY					
		Estimated Actual						
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	ndow Replacement			Componen	ts		,	Inspected
	ndow Replacement ACE BROKEN PANE			Componen Estimated			Actual	Inspected
		Units	Qty	•		Qty		Inspected
Comment REPLA	ACE BROKEN PANE	<i>Units</i> Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
Comment REPLA # Material / Labor	ACE BROKEN PANE Description / Comment			Estimated	<u>'</u>	Qty	Actual	
Comment REPLA# Material / Labor1 Windows	Description / Comment Replacement windows	Each		Estimated	<u>'</u>	Qty	Actual	
Comment REPLA# Material / Labor1 Windows2 Labor	Description / Comment Replacement windows	Each		Estimated	<u>'</u>	Qty	Actual	
Comment REPLA# Material / Labor1 Windows2 Labor	Description / Comment Replacement windows	Each		Estimated	<u>'</u>	Qty	Actual	
Comment REPLA# Material / Labor1 Windows2 Labor	Description / Comment Replacement windows	Each Hour	1	Estimated	<u>'</u>		Actual	
Comment REPLA# Material / Labor1 Windows2 Labor	Description / Comment Replacement windows	Each Hour	1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost	
# Material / Labor 1 Windows 2 Labor Other Detail	Description / Comment Replacement windows	Each Hour	1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost	

Report Run On: 5/14/2010

				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Tota
Insulation	Floor Insulation - Fbergls,Blwn	Bag	10					
	(per sq.ft.) (labor included)							
Labor	Floor Insulation - Fbergls,Blwn	Bag	10					
Other Detail								
				_		1	0 + T + +	
Field Notes: Measure 4 DO	ORS			e Sub Total:	ts		Sub Total:	Inspect
Measure 4 DO	ORS ACE BACK DOOR UNIT			Componen	ts			Inspecto
Measure 4 DO	CE BACK DOOR UNIT			Componen Estimated	ts Total		Actual	Inspecto
Measure 4 DO Comment REPLA Material / Labor		<i>Units</i> Each		Componen		Qty		
Measure 4 DO comment REPLA Material / Labor Doors	CE BACK DOOR UNIT Description / Comment	Units	Qty	Componen Estimated			Actual	
Measure 4 DO comment REPLA Material / Labor Doors Labor	Description / Comment REPLACEMENT DOOR	<i>Units</i> Each	Qty	Componen Estimated			Actual	
Measure 4 DO comment REPLA Material / Labor Doors Labor	Description / Comment REPLACEMENT DOOR	<i>Units</i> Each	Qty	Componen Estimated			Actual	
Measure 4 DO	Description / Comment REPLACEMENT DOOR	Units Each Hour	Qty 1	Componen Estimated		Qty	Actual	

Components

Inspected

Measure 3 Belly Fiberglass Loose

Report Run On: 5/14/2010

Measure 5 Smoke Detector is Needed				Componen	its	Inspected			
C	comment								
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
Į									
			Work Or	rder Gra	nd Total:		Gran	d Total:	